

WARNING LASER LEVEL VERTICAL & HORIZONTAL

Any piece of equipment can be dangerous if not operated properly. <u>YOU</u> are responsible for the safe operation of this equipment. The operator must carefully read and follow any warnings, safety signs and instructions provided with or located on the equipment. Do not remove, defeat, deface or render inoperable any of the safety devices or warnings on this equipment. <u>IF</u> any safety devices or warnings have been removed, defeated, defaced or rendered inoperable, <u>DO NOT USE THIS</u> **EQUIPMENT!!!**

WARNING: Plastic cases and product plastic housings made from polycarbonate or other plastics can expose you to chemicals including bisphenol A, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information, go to www.P65warnings.ca.gov







Points and lines can be used simultaneously



Keep these instructions with the instrument.

If the person receiving this handout will not be the user of the equipment, forward these instructions to the operator.

<u>IF</u> there is any doubt as to the operation or safety of the equipment,

DO NOT USE!!! CALL A TOOL SHED IMMEDIATELY!!!

FAILURE TO FOLLOW THESE INSTRUCTIONS COULD RESULT IN INJURY OR DEATH